: HINGE BRACKET, GAS SPRING

Monday, 16/10/2006 7:47:54 AM

User:

Linda Lacelle

Process Sheet

Cüstomer

: CU-DAR001 Dart Helicopters Services

Job Number

: 28949

Estimate Number

: 10179

P.O. Number This Issue

Written By

:N/A : 16/10/2006

S.O. No. : N/19

Prsht Rev.

: NC

First Issue **Previous Run** : 16/10/2006

: SMALL /MED FAB Type

: 28976

Checked & Approved By Comment

Reformat

KJ/RF Est Rev:E Now on Waterjet 06-10-15 JLM

Drawing Number Project Number **Drawing Revision**

Drawing Name

Part Number

Material

Due Date

: N/A : D

:NA

: D2144

D2144 REV. D

: 19/10/2006

Qty:

40 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: 304/316 .063 Sheet

1.0

2.0

M304S16GA

Comment: Qty.:

0.0945 sf(s)/Unit Total: 3.7800 sf(s)

304/316 .063 Sheet 16GA

Batch: M/01463 WATER JET

Comment: FLOW WATER JET

1-Cut as per Dwg D2144

Dwg Rev: D Prog Rev: ________

2-Deburr if necessary

3.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE





Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0 QC8 SECOND CHECK



Comment: SECOND CHECK



5.0 *

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr if necessary

User: Linda Lacelle **Process Sheet** Drawing Name: HINGE BRACKET, GAS SPRING Customer: CU-DAR001 Dart Helicopters Services Job Number: 28949 Part Number: D2144 Job Number: Seq. #: Description: **Machine Or Operation:** BRAKE NC NC BRAKE 6.0 Comment: NC BRAKE Rev: Form as per Dwg D2144 INSPECT WORK TO CURRENT STEP 7.0 Comment: INSPECT WORK TO CURRENT STEP 8.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FAB RESOURCE 1 1- Weld comer as per Dwg D2144 & QSI 004 2- Grind flush VISUAL WELDING INSPECTION 9.0 QC9 **Comment: VISUAL WELDING INSPECTION** INSPECT WORK TO CURRENT STEP 10.0 QC5 60. 25 Comment: INSPECT WORK TO CURRENT STEP POWDER COATING 11.0 POWDER COATING M101575 Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3, INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 QC3 Comment: INSPECT POWDER COAT 13.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 f306/10/26 Identify and Stock Location: 57~ · Lolel10127

Form: rprocess

Monday, 16/10/2006 7:47:54 AM

Date:

Page 2

Date:

Monday, 16/10/2006 7:47:55 AM

User:

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: HINGE BRACKET, GAS SPRING

Job Number: 28949

Part Number: D2144

Job Number:



Seq. #:

Machine Or Operation:

Description:

14.0

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion








i	DESIGN BW	DRAWN, BY	DART AEROSPA HAWKESBURY, ONTARIO	
	CHECKED	APPROVED	DRAWING NO.	REV. D
	W .	147	D2144	SHEET 2 OF 2
	DATE		TITLE	SCALE
	98.10.08		HINGE BRACKET	1:1

085

SUBJECT TO AMENDMENT WITHOUT NOTICE

RELEASED (19 1/2)



D2144 FLAT PATTERN

MATERIAL: AISI 304/316-2B SS, 0.063 THICK TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED ALL DIMENSIONS ARE IN INCHES

DART AEROSPACE LTD	Work Order:	28949	
Description: Hinge brocket, GAS Spains	Part Number:	Da144	
Inspection Dwg: 2194 Rev:		Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype						
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
00.171	+0.005-0.001	0.171	J		VerN	
0.257	10.006-0.001	0.257	V		Yern	
\$0.320	10006-0.001	0.320	\		Vern	
4.126	41-0.010	4.128	V		VEYN	
3.294	4-0.010	3.300	. (Yern	
0.340	41-0.010	0.342	V		vern	
1.000	+1-0.010	1.002	V		VLVN	·
1.660	+1-0.010	1.662	\checkmark		vern	
1.958	+1-0.010	1.959	\checkmark		Vern	
2.312	H-0.010	2.312	V		verN	·
			·			
				¥ e;		
	·		`			
			Ì			· · · · · · · · · · · · · · · · · · ·
		·	1			
						· · · · · · · · · · · · · · · · · · ·
		*				

Measured by:	M. M	Audited by:		Prototype Approval:	-
Date:	06 10 17	Date:	16:10:20	Date:	

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	<u></u> j